

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ Import Vehicles

CAMPAIGN No.	4044	DATE	Apr. 26. 2017
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain light-duty trucks, the maximum load label affixed on the rear body indicates incorrect loads. As such, these vehicles do not meet the requirements prescribed in the "Safety Regulations for Road Vehicles" , Article 18-8.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TKG-XZU710M	[HINO Dutro]	2012~2016	15
TKG-XZU710	[Toyota Dyna 400] [Toyota Toyoace G45]	2013~2016	12
		TOTAL	27