

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2475	DATE	2017/5/11
MANUFACTURE	Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	<p>On some E-Class vehicles (213 platform) with weight sensing system, the seat occupancy detection control unit on the passenger side might be incorrectly installed. Should the seat be in the vicinity of the rearmost and lowest position this could lead to a kinked pressure hose, whereby a misclassification of the front-seat passenger could occur.</p> <p>The front-seat passenger could be falsely identified as a child seat by the dynamic algorithm while driving.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
RBA-213042C	E200	2017	2,559
RBA-213242C	E200 station wagon	2017	1
DBA-213043C	E200 4MATIC	2017	63
LDA-213004C	E220d	2017	7
RBA-213045C	E250	2017	278
RBA-213071	E400 4MATIC	2017	20
CBA-213064	Mercedes AMG E43 4MATIC	2017	4
		TOTAL	2,932