

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2476	DATE	2017/5/11
MANUFACTURE	Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	On certain C-Class vehicles (204 platform) the bolt connection of the steering coupling might have been incorrectly torqued. Should the steering coupling bolt connection be incorrectly torqued, it might loosen due to vibrations during vehicle operation.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-204249	C180CGI Wagon	2014	1
DBA-204248	C200CGI Wagon	2014	3
ABA-204507	C63 AMG	2014	2
TOTAL			6