

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	Gai-2470	DATE	18/May/2017
MANUFACTURER	Automobiles Volvo Car Corporation (Japanese Importer: Volvo Car Japan Limited)		
DESCRIPTION OF DEFECT	Bolts used to assemble the inflatable curtain (IC) may break. When affected bolts are used and assembled an internal chemical process within the bolt may start. This may after a certain time period (about 48 hours) result in a bolt breakage. The corrective action is to replace the affected bolts.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
VOLVO	[V90]	2017	4
	[V90CC]	2017	30
	[XC90]	2017	111
		TOTAL	145