

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ /Import Vehicles

CAMPAIGN No.	Gai-2471	DATE	18/May/2017
MANUFACTURER	Automobiles Volvo Car Corporation (Japanese Importer: Volvo Car Japan Limited)		
DESCRIPTION OF DEFECT	The car may not start after having been parked. A software deviation in the brake hydraulic unit. The corrective action is to upgrade the VDDM software.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
VOLVO	[XC90]	2016-2017	1277
	[V90CC]	2017	1
		TOTAL	1278