

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2482	DATE	May 25 th , 2017
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	The defect involves the inflator of the affected front and/or side airbags (side and head airbag). Due to a fault in the supplier's production process, the possibly affected airbag may not deploy, although triggered properly in the event of an accident.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-4P30	「BMW 440i」	2016	8
DBA-HS15	「BMW X1 xDrive 18i」	2016	7
LDA-HT20	「BMW X1 xDrive 18d」	2016	5
		Total	20

This recall was announced on February 6th, 2017 Gai-2433. Since additional vehicles have been found to be affected, added vehicles will be announced with this recall Gai-2482.