

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

|                       |  |      |             |
|-----------------------|--|------|-------------|
| CAMPAIGN No.          | 4048   | DATE | May 25,2017 |
| MANUFACTURER          | DAIHATSU   |      |             |
| DESCRIPTION OF DEFECT | <p>Due to improper assembly position of the dust boot in the front left driveshaft, it is possible that the bellows of dust boot come in contact with each other along with vehicle vibration while driving, causing the dust boot to get worn in an early. Abrasion could progress over time, possibly leading to breakage of the dust boot and grease leak. In the worst case, it could cause a loss of drive.</p> |      |             |

| TYPE       | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|------------|-----------------|---------------------|-------------------|
| DBA-LA250S | CAST            | 2015-2016           | 30,539            |
| DBA-LA260S |                 |                     | 9,814             |
| DBA-LA250A | PIXIS JOY       | 2016                | 683               |
| DBA-LA260A |                 |                     | 264               |
| TOTAL      |                 |                     | 41,300            |