

## Vehicle Safety/Pollution Recall Campaign in Japan

Import Vehicles

|                       |   |      |               |
|-----------------------|---|------|---------------|
| Campaign No.          | Gai-2486  | Date | May 31 , 2017 |
| Manufacturer          | Jaguar Land Rover Limited<br>( Japanese Importer : Jaguar Land Rover Japan Limited )  |      |               |
| Description of defect | <p>A concern has been identified where the installation of the underfloor fuel pipe assembly on Jaguar XF 2.0L GTDi 2013 to 2015MY vehicles does not meet the design clearances as stated in Jaguar Land Rover's design rule standard. This has resulted in insufficient clearance between the underfloor fuel pipes and the vehicle under shield and body leading to a chafe condition.</p> <p>There have been no reported accidents, injuries or fires as a result of this concern.</p> |      |               |

| Type      | Commercial name | Model year recalled | Number of vehicles |
|-----------|-----------------|---------------------|--------------------|
| CBA-J05PC | 「Jaguar XF」     | 2013-2015           | 895                |
| Total     |                 |                     | 895                |