

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	4054	DATE	June 1 ,2017
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		<p>On certain heavy-duty sightseeing buses, due to inappropriate joint construction of the air conditioning cover and the roof, the fastener made of resin tightening the cover may be detached, causing the cover to become loose and making the gap between the roof and the cover if the strong wind is blown from the back of the roof. If the even stronger wind is blown from the side, the cover may be damaged and drop, resulting it to disturb the traffic in the worst case.</p>	

TYPE	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
ADG-RU1ESAJ PKG-RU1ESAJ	[ISUZU GALA]	2005-2008	935
ADG-RU8JHAJ BDG-RU8JHAJ		2006-2008	105
		TOTAL	1,040