

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4059	DATE	June.8, 2017
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	<p>As concerns tailgate open stay of gas-charged type, its outer casing end cap may be unsuitably coated whereby the end cap can be corroded by salt in localities with high humidity, especially in coastal areas where salt is present in moist sea air. While the vehicle continues in service, such corrosion would advance, causing the outer casing to swell and the end cap to crack, eventuating in the outer casing fracture into fragments when the tailgate is opened, and such fragments could, in the very worst case, cause injury to the people nearby.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-JF1	「N-BOX SLASH」	2014~2016	23,135
DBA-JF2			4,237
		TOTAL	27,372