

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2493	DATE	Jun. 13 2017
MANUFACTURER	Mercedes-Benz (Japanese importer : Mitsubishi Fuso Truck and Bus Corporation )		
DESCRIPTION OF DEFECT	The spacer on engines for articulated buses, preventing the fuel hoses from adjoining, lacks retaining force. Therefore, the spacer may loosen or fall off due to engine vibration. Continued use of the vehicle may cause the fuel hoses to adjoin and create a hole, resulting in fuel leakage. In the worst case, a fire will occur.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
Unclear model	「Citaro-G」	2007~2011	25
TOTAL			25