

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIN No.	Gai -2483	DATE	16 June, 2017
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG (Japanese Importer: Porsche Japan KK)		
DESCRIPTION OF DEFECT	Fine hairline cracks can occur on the filter flange of the fuel pump on the affected vehicles. As a result, fuel can seep out causing a smell of fuel.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
ABA-95BCNC	Macan	2015	468	
		2016	498	
ABA-95BCNCA		2015	10	
		2016	10	
ABA-J1H1		2017	1024	
ABA-J1H1A			7	
ABA-J1H2		Macan GTS	2017	723
ABA-J1H2A				255
ABA-95BCTM		Macan S	2015	694
			2016	419
	2017		653	
ABA-95BCTMA	2015		103	
	2016		37	
	2017		36	
DBA-95BCTL	Macan Turbo		2015	234
			2016	254
			2017	188
DBA-95BCTLA			2015	284
		2016	178	
		2017	95	
ABA-J1H3			2017	81

ABA-J1H3A		2017	27
		TOTAL	6278