

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

June 23 2017

To Mr.Minister, the Ministry of Land, Infrastructure, Transport and Tourism

Name and Company
President, Isao Watanabe A to Z Co., Ltd.

Address 862-3 Mashito, Kasukabe, Saitama

CAMPAIGN No.	4060	Date	June 23rd 2017
MANUFACTURER	Nissan DBF-VM20/(Product name:NV200 Vanette Camping)		
DESCRIPTION OF DEFECT	Wrong placement of front direction indicator : When we installed front direction indicators of our camping cars, product name NV200 Vanette Camping, we failed to place them at the regal position.(under the regulation, front direction indicators must be placed within 400mm from the outer edge.) They are not suitable for Safety standards for road transport vehicles article 41.		
Improvement measures	Front bumper of the cars to be exchanged to positon direct indicators at the regulated place on all NV200 Vanette Camping.		
Announcement to vehicle users and/or automobile maintenance companies	<ul style="list-style-type: none"> • Users : to contact directly by email and/or telephone call. • Automobile maintenance companies: We know all our users, thus no need to announce to automobile maintenance companies. • Replacement Compiled Vehicles: Place # 4060 sticker on the door striker at the side of driver's seat. 		

Vehicle Make	Model	Product Name	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Note
Nissan	DBF-VM20Kai	NV200 Vanette Camping	October 23rd 2012~October 16th 2016	118	
Total				118	