

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	GAI-2501	DATE	26 June 2017
MANUFACTURER	MASERATI S.p.A. (Japanese Importer: Maserati Japan Ltd.)		
DESCRIPTION OF DEFECT	Incorrect design of driver wiring harness layout with following potential interference with adjustment motor housing.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ABA-MG30C	GHIBLI	2014,2015,2016,2017	1,158
ABA-MG30A	GHIBLI	2014,2015,2016,2017	1,388
ABA-MG30AA	GHIBLI	2014,2015,2016,2017	325
FDA-MG30D	GHIBLI	2015,2016	118
ABA-MQP30C	QUATTROPORTE	2015,2016,2017	108
ABA-MQP30A	QUATTROPORTE	2014,2015, 2016,2017	483
ABA-MQP30AA	QUATTROPORTE	2014,2015,2016	129
ABA-MQP38A	QUATTROPORTE	2014,2015,2016,2017	337
ABA-MLE30D	LEVANTE	2017	78
ABA-MLE30E	LEVANTE	2017	152
		TOTAL	4,276