

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2508	DATE	June 26 th , 2017
MANUFACTURER	ALPINA Brukard Bovensiepen GmbH + Co. KG (Japanese Importer: Nicole Racing Japan LLC)		
DESCRIPTION OF DEFECT	Due to improper manufacturing of the joint disk, which connects the propeller shaft and transmission on power transmission mechanism, the joint disk might not be robust enough. Thus, the disk might be damaged by drive torque. When keep driving under this condition, noise may occur while driving, then the propeller shaft might come off, and in worst case, it is not possible to drive further.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-3K30	B3S Biturbo	2011	14
	B3S Biturbo Touring	2011	4
	B3S Biturbo Coupe	2011	5
	B3S Biturbo Cabrio	2011	3
		TOTAL	26