

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2502	DATE	June 29, 2017
MANUFACTURER	Audi (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	<p>Foreign particles in the coolant can lead to a blockage in the additional coolant pump and cause the pump to overheat.</p> <p>A software update, which deactivates the additional coolant pump in the event of a malfunction, must be carried out on the affected vehicles. The additional coolant pump must also be replaced if the malfunction is known to have occurred on that vehicle.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-8KCDNA	A4 Allroad	2013	236
DBA-4GCDN	A6 2.0/ A6 Avant 2.0	2014	309
DBA-8FCDNF	A5 Cabriolet 2.0Tq	2012 – 2017	403
DBA-8KCDN	A4 2.0T/ A4 Avant 2.0T	2013 – 2015	12,097
DBA-8KCDNF	A4 2.0Tq/ A4 Avant 2.0Tq	2013 – 2015	5,584
DBA-8TCDNF	A5 2.0Tq	2012 – 2016	665
DBA-8TCDNL	A5 SB 2.0Tq	2012 – 2016	6,444
		Total	25,738