

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import~~ Vehicles

CAMPAIGN No.	Gai-2509	DATE	June 30 th , 2017
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to the inappropriate production of the fuel delivery line of the diesel engine, the fuel delivery line may have wrinkles on the inner layer in single cases. Thus, when keep driving under this situation, the fuel pulsation pressure may lead gradually to fuel leakage.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-3D20	BMW 320d	2014-2015	4,461
		TOTAL	4,461