

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4066	DATE	July.3.2017
MANUFACTURER	KUBOTA Corporation		
DESCRIPTION OF DEFECT	Due to lack of waterproof performance of wire harness, corrosion of electricity terminal might occur. At the worst case the engine stops during operation then the vehicle can't travel.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDM-R430E	「R430E」	2016 to 2017	83
	「6SDTL8」	2016 to 2017	72
YDM-R530E	「R530E」	2016 to 2017	117
	「6SDTL10」	2016 to 2017	9
YDM-R630E	「R630E」	2016 to 2017	23
	「6SDTL12」	2016	7
		TOTAL	311