

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	4072	DATE	July 3, 2017
MANUFACTURER	Kawasaki Heavy Industries, Ltd.		
DESCRIPTION OF DEFECT	<p>The internal component in the fuel pump may be excessively worn in use by</p> <ol style="list-style-type: none"> 1) The fluctuation of voltage supplying from the vehicle to the fuel pump 2) Variation of the fuel pump in production <p style="text-align: center;">resulting in malfunction of the fuel pump, and or impossible to engine start.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Notes
JBK-EX250K	Ninja 250R	2008 - 2012	19,990	
JBK-LX250S	KLX250	2008 - 2016	4,677	
JBK-LX250V	D-TRACKER X	2008 - 2016	4,396	
TOTAL			29,063	