

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4077	DATE	July. 11. 2017
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain heavy duty trucks, due to the insufficient strength of the stabilizer arm of the rear air suspension, the arm may crack if the vehicle turns frequently. Therefore, if the vehicle is operated under the condition continuously, in the worst case, the stabilizer arm may break, resulting it unable to run.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KL-GN2PPHA	[HINO Super Dolphin]	2002~2003	4
KS-GN2PPWG PK-GN2PPWG	[HINO Profia]	2003~2007	152
BDG-GN1APYG		2007~2010	137
LDG-GN1APBG LKG-GN1APBG QKG-GN1APBG		2010~2013	294
		Total	687