

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	4064	DATE	JUL-14-2017
MANUFACTURER	YAMABIKO CORPORATION President & C.E.O. Yoshiaki Nagao		
SUMMARY OF DEFECT	As for cooling system (radiator drain hose, radiator reservoir hose) and fuel system (fuel supply hose from fuel tank to engine), due to improper assembly instruction, surface of these hoses may be damaged by hose fixture clip. As a result, continuing operation with this condition may lead coolant leakage from the hoses in cooling system and/or fuel leakage from the hose in fuel system.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
S55D	KIORITZ SPEED SPRAYER SSV553 F	2010~2017	615
S65A	KIORITZ SPEED SPRAYER SSV654 F	2012~2017	169
S53B	KIORITZ SPEED SPRAYER SSVH535 F	2011~2016	266
		TOTAL	1050