

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	Gai-2420	DATE	18/July/2017
MANUFACTURER	Automobiles Volvo Car Corporation (Japanese Importer: Volvo Car Japan Limited)		
DESCRIPTION OF DEFECT	<p>1. Under certain specific driving conditions, such as high load (ex: trailer) or high speed immediately after cold start, specifically in cold climate, the engine temperature gradient in the cylinder head may be too steep. Consequently, this could lead to localized high stress in the cylinder head material, which may cause damages in the cylinder head. The corrective action is to replace the new improved manifold gasket together with modification to the coolant by-pass valve. This will result in a less steep temperature gradient during cold start.</p> <p>2. High ambient temperatures in warm climate, combined with extended idling and certain driving patterns, causes the bleeder hose material to crack. The corrective action is to replace the bleeder hose.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
VOLVO	[S80]	2011	60
	[V70]	2011 - 2015	2696
	[V60]	2011 - 2015	12299
	[S60]	2011 - 2015	5486
	[V40]	2013 - 2015	15559
	[V40CC]	2014	199
		TOTAL	36299