

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4070	DATE	Jul. 20, 2017
MANUFACTURER	SUBARU CORPORATION		
DESCRIPTION OF DEFECT	There is no “i-Size child restraint system approved seating position list” on the owner’s manual, therefore, it does not comply with Safety Regulations Article22-3, Detail Notice Article30 (Regulation No.16 Revision6). There is no functionality problem with child restraint system when it is fixed.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GK2	「IMPREZA」	2016~2017	1,004
DBA-GK3		2016~2017	635
DBA-GK6		2016~2017	2,030
DBA-GK7		2016~2017	3,796
DBA-GT2		2016~2017	5,967
DBA-GT3		2016~2017	3,919
DBA-GT6		2016~2017	6,959
DBA-GT7		2016~2017	12,746
DBA-GT3		「XV」	2017~2017
DBA-GT7	2017~2017		3,882
		TOTAL	42,080