

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4 0 8 7	DATE	July.24.2017
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	<p>In brake master cylinder, due to inappropriate piston seal shape, the seal may get rolled up when the brake pedal is operated.</p> <p>Therefore, brake fluid leaks from the seal part, and a warning light turns on, in an extreme case, the braking force decreases, and braking distance might get longer.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DBA-TE52	ELGRAND	2014	11,188
DBA-TNE52		~	2,672
DBA-PE52		2017	712
DBA-PNE52			363
		TOTAL	14,935