

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2519	DATE	July 31, 2017
MANUFACTURER	Audi (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	<p>Panorama sunroof manufactured model, water can seep into the vehicle's headliner if the water drain in the area of the panorama sunroof is not functioning properly. If enough moisture accumulates, the foam adjacent to the gas generator of the curtain airbag can become wet. This can cause corrosion on the gas generator.</p> <p>The gas generators for the curtain airbags (on both sides of the vehicle) must be checked on the affected vehicles.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-8RCALF	Q5 3.2q	2011 – 2012	51
ABA-8RCDNF	Q5 2.0Tq	2011 – 2012	198
ABA-8RCNCF	Q5 2.0Tq	2013 – 2017	482
ABA-8RCTVF	Q5 3.0Tq	2013 – 2014	65
ABA-8RCTXF	SQ5	2014 – 2016	316
DAA-8RCHJF	Q5 Hybrid	2013 – 2014	44
		Total	1,156