

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import~~ Vehicles

Campaign No.	4083	Date	Aug. 2, 2017
Manufacture	CATERPILLAR JAPAN LLC.		
Description of Deffect	Front axle mount bolts and Drive shaft joint bolts may have not been applied correctly. Then, some of fastners may be loosen and the drive train above can drop off.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
WDP-AY4	「910K」	2017	22
		TOTAL	22