

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2461	DATE	August, 4,2017
MANUFACTURER	Automobili Lamborghini SpA (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	This defect of EVAP system component cause a condition that fuel vapors wouldn't be treated appropriately, and when bad condition is piled by specific operation, there is possibility that the fuel vapors which isn't treated appropriately touches hot part of exhaust system.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-47L539	Aventador LP700-4	2011 - 2017	569
	Aventador LP720-4		
	Aventador LP750-4		