

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	4095	DATE	Aug. 10, 2017
MANUFACTURER	MITSUBISHI MAHINDRA AGRICULTURAL MACHINERY CO.,LTD.		
DESCRIPTION OF DEFECT	On the engine of the agricultural tractor, HC(Hydrocarbon) density in an exhaust gas is increased, Such exhaust gas comes into EGR cooler, Carbon deposit is generated and may adhere to EGR valve probably due to an improper program of the engine control unit. Therefore, EGR valve does not move smoothly due to HC deposition. As a result, there is risk that the engine output is limited.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDN-GT55B	「GM550」	2015-2017	86
YDN-GT55C	「GA550」	2016-2017	65
	「GAK550」	2016-2017	17
		TOTAL	168