

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	4093	DATE	August 24 ,2017
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		<p>There are medium-duty trucks where the lock plate to secure nuts used for installing the shackle for the right-hand front leaf spring was not appropriately fitted. Consequently, if the medium-duty trucks in question continue to be used in such a state, the aforementioned nuts may become loose, which may, in the worst case, lead to the shackle falling off.</p>	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
SKG-FRR90S2 SKG-FRR90T2 TKG-FRR90S1 TKG-FRR90S2 TKG-FRR90T2	[FORWARD]	2014-2015	19,066	
SDG-FRS90S1 SDG-FRS90S2 SKG-FRS90S2 TKG-FRS90S2		2014-2015	81	
SKG-FSR90S2 SKG-FSR90T2 SPG-FSR90S2 SPG-FSR90T2		2014-2015	1,114	
SDG-FSS90S1 SDG-FSS90S2 SKG-FSS90S2 SPG-FSS90S2		2014-2015	36	
QKG-FTR34S2 QKG-FTR34T2 QPG-FTR34S2 QPG-FTR34T2		2014-2015	502	
LKG-FTR90S2 LKG-FTR90T2 LPG-FTR90S2 LPG-FTR90T2		2014-2015	1,254	
SDG-GSR90S2		2014	9	
		TOTAL	22,062	