

CHILD RESTRAINT SYSTEM SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Import item

CAMPAIGN No.	装外-9	DATE	20-Sep-2017
MANUFACTURER	RECARO Child Safety Co., Ltd.		
DESCRIPTION OF DEFECT	<p>The child restraint system's shoulder belt loosens during collision because the stopper function of the harness belt adjuster that controls the expansion and contraction of the shoulder belt does not work. It might be not able to reliably restrain the occupant.</p> <p>The cause is that the repair in the manufacturing process was inappropriate.</p>		

COMMERCIAL NAME	TYPE	CLASSIFICATION	MODEL YEAR	NUMBER OF CHILD RESTRAINT SYSTEMS
			RECALLED	
Zero.1 Smile Giraffe Brown	Zero.1 E1-04301325	GO+/1	KS01024226, KS01024239, KS01024240, KS01024241, KS01024248, KS01024305, KS01024314, KS01024330, KS01024332, KS01024390, KS01024393, KS01024395, KS01024401, KS01024437, KS01024439, KS01024447, KS01024451, KS01024452, KS01024456, KS01024460 (Manufacturing date from Aug 5 th 2016 until Aug 17 th 2016)	20 pcs
Total				20 pcs