

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2533	DATE	Sep. 22. 2017
MANUFACTURE	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	In the course of quality analysis at BMW Motorrad, it was determined that for a few motorcycles, the screw connection of the right fixed-bearing stud of the rear wheel swinging arm on the frame loosens. This in turn may result in bad vehicle drivability.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBL-R12JB	BMW R nineT	2014-2017	1,267
R NINET	BMW R NINET	2014	4
		TOTAL	1,271