

## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2544	DATE	2017/9/28
MANUFACTURE	Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd. )		
DESCRIPTION OF DEFECT	On certain Mercedes-Benz V-Class vehicles some of the intended weld spots on the rear cross-member and in the same area on the longitudinal beams might have not been applied. Due to a failure in the software of the welding robot, the weld spots were not executed on the affected vehicles. It cannot be ruled out that the missing spot weld might impact the crash characteristics of the vehicle in the event of a crash.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-447811	V220d	2016	1
		<b>TOTAL</b>	1