

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2536	Date	October 5, 2017
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	In the fuel device, the top of the flange may deteriorate early by wetting with rainwater from outside due to inappropriate the mounting position of the fuel pump filter flange. As the result, due to the pressure from fuel, cracks may occur in the flange during continuous usage and then fuel may leak from the area.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
Unknown	VW Touareg 3.2 V6	MY2005	1
	VW Touareg 3.2 V6	MY2003	5
	VW Touareg 4.2 V8	MY2003-2005	8
GH-7LAZZS	VW Touareg 3.2 V6	MY2003-2004	1,712
GH-7LAXQA	VW Touareg 4.2 V8 Air sus	MY2003-2007	1,487
GH-7LAXQS	VW Touareg 4.2 V8	MY2004-2006	23
GH-7LBJNA	VW Touareg W12 sports	MY2005-2007	251
GH-7LBMVA	VW Touareg 3.2 V6 Air sus	MY2005-2007	630
GH-7LBMVS	VW Touareg 3.2 V6	MY2005-2007	3,127
ABA-7LBARA	VW Touareg 4.2 V8 Air sus	MY2007-2009	389
ABA-7LBHKA	VW Touareg 3.6 V6 Air sus	MY2007-2009	522
ABA-7LBHKS	VW Touareg 3.6 V6	MY2007-2010	2,214
		Total	10,369