

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

| | | | |
|-----------------------|---|------|------------------|
| CAMPAIGN No. | 4 1 2 9 | DATE | October 23, 2017 |
| MANUFACTURE | Topre Corporation | | |
| DESCRIPTION OF DEFECT | <p>Because the installation position of U-bolt for which fix the main frame of the refrigerated freezing container and the chassis frame (hereinafter referred to as " container U-bolt ") is inappropriate, the container U-bolt interfere with U-bolt for which fix the left leaf spring and the rear axle of truck chassis (hereinafter referred to as " leaf spring U-bolt "), on the rough road driving.</p> <p>Therefore, in use as it is, the container U-bolt and the leaf spring U-bolt might be damaged. In addition, the vehicle running stability might be lost due to the displacement of leaf spring in the worst case.</p> | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|--------------|-----------------|---------------------|-------------------|
| BKG-NPR85AN | ELF | 2015 | 1 |
| PA-NPR81N | | 2016 | 1 |
| TFG-NPR82ZAN | | 2015~2017 | 8 |
| TKG-NPR85AN | | 2015~2017 | 4 |
| TKG-NPR85YN | | 2015~2016 | 62 |
| TKG-NPS85AN | | 2016~2017 | 25 |
| TRG-NPR85AN | | 2015~2016 | 158 |
| TSG-NPR85AN | | 2016~2017 | 263 |
| TPG-NPR85AN | | 2015~2017 | 2,276 |
| TPG-NPR85YN | | 2015~2017 | 33 |
| TPG-NPS85AN | | 2015~2017 | 43 |
| TRG-LPR85AN | | TITAN | 2015~2017 |
| TPG-LPR85AN | 2016 | | 1 |
| TPG-LPR85YN | 2015 | | 1 |
| | | TOTAL | 2,885 |