

## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2561	DATE	2017/11/16
MANUFACTURE	Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd. )		
DESCRIPTION OF DEFECT	On certain G-Class vehicles (463 platform) with 4,0l 8-cylinder gasoline engine (M176) an incorrect data input could cause a misinterpretation of fuel temperature sensor signals as an electrical fault. This would lead to an incorrect activation of the malfunction indicator lamp (MIL). In addition to the incorrect activation of the malfunction indicator lamp (MIL) the lambda control would be slightly affected. In this case an exceedance of the certified emission values could not be excluded, however the statutory limits regarding emission values won't be exceeded.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-463234	G550	2016	1
		2017	171
		TOTAL	172