

## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2562	DATE	2017/11/16
MANUFACTURE	Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd. )		
DESCRIPTION OF DEFECT	On certain S-Class vehicles (217/222 platform) with gasoline engines the software of the engine control unit and the fuel system control unit might not meet the specification. Due to faulty software logic in the control units, the malfunction indicator lamp (MIL) will not be activated in case of a fault caused by the fuel pump control unit and thus the OBD requirements will not be met.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBA-222176C	S600	2015	84
CBA-222179C	Mercedes-AMG S65	2015	60
CBA-217379C	Mercedes-AMG S65 Coupe	2015	8
ABA-222976C	Mercedes-Maybach S600	2015	7
<b>TOTAL</b>			<b>159</b>