

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	GAI-2558	DATE	17 Nov. 2017
MANUFACTURER	MASERATI S.p.A. (Japanese Importer: Maserati Japan Ltd.)		
DESCRIPTION OF DEFECT	Fuel pump resistor, low pressure fuel pump wiring harness. Operative current comparable to the maximum allowed by the resistor with consequent failure due to cycle time fatigue absorbed		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ABA-MQP38A	QUATTROPORTE	2014,2015,2016,2017	91
		TOTAL	91