

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4142	DATE	Nov. 24,2017
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	<p>In the vacuum hose of the brake booster, there is a possibility that foreign substances have adhered to the inner face of the hoses due to improper assembly. In such a case, the check valve inserted in the hose may get stuck and negative pressure may be supplied insufficiently over time. As a result, it may cause the brake pedal effort to increase.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-M700S	BOON	2017	83
DBA-M710S			14
DBA-M900S	THOR		261
DBA-M910S			61
DBA-M700A	PASSO		484
DBA-M710A			83
DBA-M900A	ROOMY /TANK		1,979
DBA-M910A			392
DBA-M900F	JUSTY		28
DBA-M910F			12
		TOTAL	3,397