

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-2564	DATE	November 28 2017
MANUFACTURE	FCA US LLC (Japanese Importer : Fiat Chrysler Automobiles Japan Ltd.)		
DESCRIPTION OF DEFECT	<p>The clutch interlock switch may contain a return spring that fatigues. A fatigued clutch interlock switch return spring could allow the driver to engage the engine starter motor without the clutch pedal being depressed. Engaging the engine starter motor with the transmission in gear and the clutch engaged, could result in unintended vehicle movement and cause a crash without warning.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GH-TJ40S	「Jeep・Wrangler」	2006	174
		TOTAL	174