

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-2566	DATE	November 28 2017
MANUFACTURE	FCA US LLC (Japanese Importer : Fiat Chrysler Automobiles Japan Ltd.)		
DESCRIPTION OF DEFECT	The ignition switch may experience an unintended change in ignition switch position while driving. This may result in a loss of engine power, power steering assist, power brake assist or disable the airbag function. Disabling one or more of the vehicle's safety features could increase the risk of vehicle occupant injury during a crash and/or cause a crash without warning.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GH-WH47	「Jeep・Grand Cherokee」	2005-2006	874
GH-WH57	「Jeep・Grand Cherokee」	2005-2007	445
Unknown	「Jeep・Grand Cherokee」	2006-2007	56
GH-XH47	「Jeep・Commander」	2006-2007	346
GH-XH57	「Jeep・Commander」	2006-2007	248
ABA-XH47	「Jeep・Commander」	2007	114
ABA-XH57	「Jeep・Commander」	2007	73
		TOTAL	2156