

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4146	DATE	Nov. 28 2017
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some heavy-duty trucks with the high pressure air system, the selection of the air compressor is improper. The oil contained in the air compressed by the air compressor will be carbonized and accumulated in the air discharge pipe. Therefore, if the vehicle continues to be used in this condition, the air discharge pipe will be damaged by accumulated carbides, and it will be impossible to compress air. In the worst case, the vehicle will be become unable to operate.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
LKG-FP54VDR	「FUSO SUPER GREAT」	2010~2012	1,119	
LKG-FP54VER		2010~2012	188	
LKG-FP54VGR		2010~2012	61	
LKG-FU54VY		2010~2012	105	
LKG-FU54VZ		2009~2014	2,182	
LKG-FU55VZ		2010~2012	231	
LKG-FV54VZ		2010~2012	171	
QKG-FP54VDR		2010~2014	1,947	
QKG-FP54VER		2012~2014	434	
QKG-FP54VGR		2010~2014	203	
QKG-FU54VY		2011~2014	189	
QKG-FU54VZ		2011~2014	3,727	
QKG-FU55VZ		2011~2014	402	
QKG-FU64VZ		2014	1	
QKG-FV54VZ		2011~2014	327	
QPG-FP54VDR		2013~2014	4	
QPG-FP64VDR		2014~2014	45	
QPG-FP64VER		2014~2014	5	
QPG-FP64VGR		2014~2014	2	
QPG-FU54VZ		2013	1	
QPG-FU55VZ		2014	1	
QPG-FU64VY		2014~2014	3	
QPG-FU64VZ		2014~2014	52	
QPG-FU65VZ		2014~2014	13	
QPG-FV64VZ		2014~2014	6	
		TOTAL	11,419	