

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	4145	DATE	November 29, 2017
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	Some of the flange bolts which fix the hydraulic hoses and hydraulic piping of the hydrostatic transmission on loaders lack strength, and as a result, they elongate and their axial tension decreases. Therefore, if the loaders are used as they are, the bolts loosen because of vibration during operation and the oil leaks, then the hydraulic hoses, etc. come off and the machine cannot travel in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
WDR-WA126	「WA200-7」	2017	50
WDR-WA122	「WA270-7」	2017	12
WDR-WA121	「WA320-7」	2017	26
		TOTAL	88