

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4155	DATE	07/12/2017
MANUFACTURER	UD Trucks Corporation		
DESCRIPTION OF DEFECT	With regards to the wiring harness which is connected to Heavy Duty bus generator, due to improper clamping of the power supply cable and signal lines, whilst driving the signal lines may be damaged and disconnected by vehicle's vibration. If the vehicle continues operation in this condition, the vehicle may not control power generation then the battery charge become unavailable with warning lamp on. The worst case scenario is that the vehicle might become inoperable.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ADG-RA273KAN PDG-RA273KAN	-	2005-2010	250
ADG-RA273MAN PDG-RA273MAN	-	2005-2010	284
ADG-RA273PAN PDG-RA273PAN	-	2005-2010	80
ADG-RA273RBN	Space Arrow/Space Wing	2005-2008	79
ADG-RA273TAN	-	2005-2006	25
PKG-RA274KAN	Space Runner	2006-2010	572
PKG-RA274MAN	Space Runner	2006-2010	704
PKG-RA274PAN PKG-RA274PAN KAI	Space Runner	2006-2009	63
PKG-RA274RBN	Space Runner	2006-2010	194
PKG-RA274TAN	Space Runner	2006-2010	135
ADG-AA273KAN PDG-AA273KAN	Fuso Aero Star-S	2007-2009	49

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PDG-AA273MAN	Fuso Aero Star-S	2007-2009	62
PKG-AA274KAN	Fuso Aero Midi-S	2007-2010	151
PKG-AA274MAN	Fuso Aero Midi-S	2007-2009	50
PKG-AA274PAN	Fuso Aero Midi-S	2007-2010	38
		Total	2,736