

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIN No.	Gai -2568	DATE	8 December, 2017
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG (Japanese Importer: Porsche Japan KK)		
DESCRIPTION OF DEFECT	Due to a software error, there is a possibility that the enhanced seat belt diagnostic function may not detect the driver's correctly fastened seat belt on the affected vehicles. If this happens, the warning message "Driver seat belt not fastened, Fasten seat belt" will be displayed in the instrument cluster.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-G2H29A	Panamera 4S	2017	215
ABA-G2H29AX			1
ABA-G2H40A	Panamera Turbo		109
ABA-G2H40AX			8
ABA-G2H30A	Panamera		85
	Panamera 4		19
ABA-G2H30AX			1
ALA-G2H29A	Panamera 4 e-hybrid		23
ALA-G2J29A			2
			TOTAL