

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2579	Date	13,12, 2017
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	Due to improper prevention for humidity control of Driver airbag inflator, propellant inside may suffer material wear under high humidity environment with temperature changing. As a result, container of the inflator may rupture when airbag deploy.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-1KCAV	Golf 1.4/118kW	MY2009-MY2010	6
ABA-3CBWSC	Passat CC 3.6 V6 4M	MY2011	1
ABA-3CCCZF	Passat alltrack	MY2012-MY2013	2
ABA-3CCDAC	CC 1.8T	MY2013	1
ABA-6RCGG	Polo 1.4 / 63kW	MY2010	1
DBA-1KCAV	Golf 1.4/118kW	MY2011-MY2012	3
DBA-1KCAVK	Golf Cabriolet 1.4 / 118kW	MY2012	1
DBA-3CCAX	Passat Sedan 1.4T	MY2011	1
	Passat Variant 1.4T	MY2012-MY2014	4
DBA-6RCBZ	Polo 1.2 / 77kW	MY2010-MY2014	107
DBA-6RCBZW	Cross Polo 1.2 / 77kW	MY2011-MY2013	5
DBA-7NCAV	Sharan 1.4 / 110kW	MY2011-MY2012	4
DBA-AACHY	up! 1.0 / 55kW	MY2013-MY2014	20

GH-9NBKY	Polo 1.4	MY2007	737
GH-9NBTS	Polo 1.6	MY2007	350
		Total	1,243