

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	4158	DATE	December 14 ,2017
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		<p>The subject matter relates to a heat protector, which is a system to prevent transfer of exhaust heat to peripheral systems, installed on heavy-duty trucks. As there were errors made during an assembly process, the wrong heat protectors were installed to some of them. As a result, a distance between the rear end of the rearmost front tire and heat protector exceeded 400 mm. This may result in failing to comply with a safety standard that defines requirements for pedestrian protection side guard.</p>	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2KG-CXZ60CT	[GIGA]	2017	2	
2KG-CXZ77CT 2PG-CXZ77CT		2017	26	
2KG-CYE60CM		2017	2	
2PG-CYE77CZ		2017	1	
2KG-CYG60CM		2017	3	
2KG-CYJ77C 2PG-CYJ77C		2017	62	
2KG-CYL77C 2PG-CYL77C		2017	31	
2PG-CYL77CM		2017	1	
2PG-CYM77C		2017	1	
2KG-CYM77CM 2PG-CYM77CM		2017	5	
2PG-CYY77C		2017	2	
2PG-CYZ77C		2017	2	
2PG-CYZ77CJ		2017	2	
2PG-CYZ77CM		2017	3	
		TOTAL	143	