

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CANPAIGN No.	4161	DATE	Dec. 14. 2017
MANUFACTURER	SHINMAYWA INDUSTRIES LTD.		
DESCRIPTION OF DEFECT	Rear members and rear covers of garbage containers for container detachable vehicles were welded improperly, thus the welded part can be cracked due to vibration while driving and so on. Not repairing, the crack can be grown, and therefore the rear cover can drop off and disturb other traffic in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CNA5-59G	PACKER CONTAINER	1999~2005	3
CNA6-59G**		2003~2007	6
CNA7-59G**		1999~2016	75
CNA8-59G**		1998~2017	182
CNA8-59U**		2002~2003	2
CNA9-59G**		2002~2015	15
CNA10-59G**		2000~2015	20
CNR10-59G**		2001~2001	2
		TOTAL	305