

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	4163	DATE	Dec 21,2017
MANUFACTURER	TADANO LTD.		
DESCRIPTION OF DEFECT	<p>On Wheel crane braking devices there have been cases of the brake caliper caps loosening with the hydraulic pressure of actuation as a result of defective brake caliper manufacturing involving low cap installation torque. Therefore, with continued use in in this condition, there is a risk of the cap seal effectiveness being compromised, brake fluid leaking, the brake warning light turning on, and in worst cases, diminished braking ability.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UDS-T007	TADANO 「GR-250N-3」	2013-2016	1607
		TOTAL	1607