

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	4165	DATE	December 26, 2017
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	<p>When the rotary snow removal attachment is installed to a shovel loader, the battery cable may be interfered with the hydraulic hoses by vibration during travel and its cover, etc. may be damaged, because the installation instruction for the battery cable is improper.</p> <p>Accordingly, if the machine is used under this condition, the battery cable core and hydraulic hose wires may be exposed and may contact each other and cause a short circuit. In the worst case, a fire breaks out.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
W109	「WA200-5」	2003	1
SC-W109		2004 to 2006	2
EDR-WA105	「WA200-6」	2007 to 2013	23
SC-W104	「WA270-5」	2005 to 2006	3
EDR-WA103	「WA270-6」	2007 to 2013	12
TOTAL			41