

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2583	DATE	January 24, 2018
MANUFACTURER	Audi (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	<p>The sealing system may become damaged during its service life due to discrepancies during manufacture of the high-pressure pump. “Perspiration” at the flow control valve of the high-pressure pump can occur as a consequence.</p> <p>The high-pressure pump must be replaced.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-8KCNCA	A4	2014	262
ABA-8RCNCF	Q5	2013 - 2014	2,112
ABA-8VCJXF	S3 SB	2014	291
ABA-8VCJXL	S3 Sedan	2014	67
		Total	2,732